

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.



2854
09/631,869

1/6




FIG. I



COPY OF PAPERS
ORIGINALLY FILED

2854
09/631,869

2/6




FIG. 2

O
SEP 03 2002
0180
PATENT & TRADEMARK OFFICE

COPY OF PAPERS
ORIGINALLY FILED

2854
09/631,869

3/6




FIG. 3



COPY OF PAPER
ORIGINALLY FILED

2854
09/631,869

4/6




FIG. 4



COPY OF PAPERS
ORIGINALLY FILED

2854
09/631,869

5/6




FIG. 5



COPY OF PAPERS
ORIGINALLY FILED

2854
09/631,869

6/6

516

Xerox TCP/IP Port - Configuration

Port Settings

Port Name: N4025 Rm 3103

Printer Name or IP Address: 13.177.48.3

Protocol:

Raw Lpr

Raw Settings

Raw Port Number: 9100

Lpr Settings

Lpr Queue Name: raw

Lpr byte counting enabled

Bi-directional Settings

Bi-directional communication enabled

Update configuration every: 30 seconds

Update status every: 10 seconds

SNMP Community Name: public

About OK Cancel

524 528

520

FIG. 6

O I P R
SEP 9 3 2002
CURR PAPERS
ORIGINALLY FILED
PATENT & TRADEMARK OFFICE

2854
09/631,869

4/6

